



## SAFETY BULLETIN 2021001



### SAFETY NOTICE MANDATORY ACTION REQUIRED

#### IMMEDIATELY REMOVE FROM SERVICE MODELS S25/83HD+ & S28/92HD+ THAT DO NOT HAVE A BOOM WELD RETROFIT INSTALLED

**ISSUE:** CMC has been notified of incidents where the upper boom on Models S25/83HD+ and S28/92HD+ has cracked and/or broken (see photo at right). Two injuries and one fatality have been reported.

CMC is requiring that **LIFT MODELS S25/83HD+ and S28/92HD+ THAT HAVE NOT BEEN RETROFITTED MUST BE IMMEDIATELY SHUT DOWN AND REMOVED FROM SERVICE UNTIL THE RETROFIT IS INSTALLED.**

If you do not know if your model has been retrofitted or if your model was manufactured in 2021 (see plate affixed to unit), please call **1-888-831-0398** or email [inspections@cmclift.com](mailto:inspections@cmclift.com) for additional guidance.



## WARNING



- CMC has been notified of incidents where the upper boom on Models S25/83HD+ and S28/92HD+ has cracked and/or broken, which could result in death or serious injury.
- Immediately stop use of the models S25/83HD+ and S28/92HD+ that have not been retrofitted and remove them from further use.
- Please call 1-888-831-0398 or email [inspections@cmclift.com](mailto:inspections@cmclift.com) to schedule an installation of the retrofit.
- Always read and follow all instructions in the Service and Maintenance Manual and the Owner's Manual

NOTICE: THIS SAFETY BULLETIN SUPERSEDES ALL PREVIOUS CMC SAFETY BULLETIN AND/OR EMAILS RELEASED BY CMC FOR THE ISSUE AT HAND.

DATE OF ISSUE SEPTEMBER 08, 2021